## **Application for State Assent**



Photo 1: Pier F with missing and/or dislodged exterior chocks. Fenders along the building observed to be damaged and/or missing.



Photo 2: Support piles splintering and/or necking exhibiting signs that the piles are beyond the serviceable life in the current condition



## **Application for State Assent**



Photo 3: Prior to construction the building collapsed due to a snowstorm in March of 2023. The pier at this time in not in operation.



Photo 4: Original pier elevation continuing at an elevation higher than the existing bulkhead to connect to the landside buildings FFE.







Photo 5: Gaps in decking board resulting from the removal of the previously collapsed building building.



Photo 6: View of the 5-pile alignment post building and pier removal.

