



Photo No. 1.: View of Pier 'JJ' looking north.





Photo No. 2.: View of Pier 'JJ' looking toward the bulkhead.






Photo No. 3.: View of the landside connection to the bulkhead of Pier 'JJ' looking north. (Photo 12/18/2025)




Photo No. 4.: View of the landside area behind the bulkhead at Pier 'JJ' looking south. (Photo 12/18/2025)






Photo No. 5.: View of the weathered decking of Pier 'JJ'.



Photo No. 6.: View of the interior of the shed at the end of Pier 'JJ'.






Photo No. 7.: Typical splitting of the fendering observed.



Photo No. 8.: Deterioration of timber chocks and observed damage to the timber support pile.





Photo No. 9.: Deterioration to the butt of the timber support piles, typical for 50% of observed support piles.



Photo No. 10.: Splitting of the end stringer of Pier 'JJ'.