



Photo 1: View from southeast end of Coastal Side looking west



Photo 2: View east along Pond Side access






Photo 3: Facing west from coastal side



Photo 4: View west of barge to be removed

RECEIVED
JUN 18 2021
COASTAL RESOURCES
MANAGEMENT COUNCIL



Photo 5: View east along Coastal Side timber bulkhead



Photo 6: View east along Coastal Side top of slope





Photo 7: ???



Photo 8: View north from RR track crossing

RECEIVED
JUN 17 2021
COASTAL RESOURCES
MANAGEMENT COUNCIL



Photo 9: Omega Pond Dam



Photo 10: Omega Pond dam

RECEIVED
JUN 17 2021
COASTAL RESOURCES
MANAGEMENT COUNCIL



Photo 11: Vegetation adjacent Omega Pond



Photo 12: Vegetation adjacent Omega Pond

RECEIVED
JUN 17 2021
COASTAL RESOURCES
MANAGEMENT COUNCIL



Photo 13: Vegetation adjacent Omega Pond



Photo 14: Deteriorating coastal decking

RECEIVED
JUN 17 2021
CITY OF CHARLOTTE
MANAGEMENT COUNCIL



Photo 15: West side shoreline looking south



Photo 16: Coastal vegetation

RECEIVED
JUN 17 2021
COASTAL RESOURCES
MANAGEMENT COUNCIL



Photo 17: Deteriorating barge to be removed



Photo 18: Southwest tip of coastal side

RECEIVED
JUN 17 2021
COASTAL RESOURCES
MANAGEMENT COUNCIL