



Photo 1: The upland area at 2 Shell Road looking southwest.



Photo 2: The lower terrace associated with 2 Shell Road looking southwest. Structures include a concrete seawall (left) and stone gravity retaining wall (right).



Photo 3: Cobble beach associated with 2 Shell Road looking southwest.



Photo 4: The upland area at 4 Shell Road looking northeast.



Photo 5: The lower terrace and stone gravity retaining wall associated with 4 Shell Road looking west.




Photo 6: Concrete seawall and cobble beach associated with 4 Shell Road looking northeast.

