


Woonasquatucket River - Promenade District CURRENT CONDITIONS IN SAMP AREA



- Bike Path
- Railings
- benches
- Structural Shoreline
- Vegetated Bank
- SAMP Boundary

0 1,000 2,000 Feet



View Toward Mall



Overgrown Vegetation



Public Benches



Pleasant Valley Stream



Typical Vegetation



Bike Path



Map By Austin Becker and Eivy Monroy
Data provided by RIGIS and CRC
02/2008