

ATTACHMENT – SITE PHOTOGRAPHS



Photo 1: Aerial image of project site (www.nearmap.com, dated March 27th, 2025).



Photo 2: Existing top of revetment and buffer (looking west).



ATTACHMENT – SITE PHOTOGRAPHS (continued)



Photo 3: Existing revetment; taken from existing stairs looking west.



Photo 4: Existing revetment; taken from existing stairs looking east.

RECEIVED
9/24/2025
COASTAL RESOURCES
MANAGEMENT COUNCIL

ATTACHMENT – SITE PHOTOGRAPHS (continued)



Photo 5: Existing stairs looking west.



Photo 6: Existing area of proposed infill structural shoreline protection.

RECEIVED
9/24/2025
COASTAL RESOURCES
MANAGEMENT COUNCIL